	Software Release Notes
Models Affected	No5101
Version	19

To update via Ethernet:


- Ensure the No5101 has a valid internet connection.
- Turn on the No5101.
- Press the Home button two times on the remote or in the Mark Levinson 5Kontrol App to bring up the Settings menu.
- Press the “^” (up arrow) button three times to navigate to Firmware Update. Press Enter on the remote.
- If there is an available firmware update the display will show the update. Press Enter on the remote to start the update.
- To check your software version, press the Home button two times on the remote; then press the “^” (up arrow) button one time to navigate to System Info. Press Enter to display the Software Version.

To update via USB:

- Download the firmware file from the product page at MarkLevinson.com or download link you may have received from our Customer Service personnel. Unzip it if necessary and save it to the root folder of a FAT32 formatted USB drive (so they are only files on the USB drive).
- Turn on the No5101.
- Insert the USB drive into the USB socket on the rear of the No5101.
- Approximately 20 seconds later the update message will be displayed. Press Enter on the remote to begin the update.
- When display shows Remove USB disk, remove USB drive.
- When update is complete, the unit will reboot.
- To check your software version, press the Home button two times on the remote; then press the “^” (up arrow) button one time to navigate to System Info. Press Enter to display the Software Version.

HARMAN International Industries, Incorporated, 8500 Balboa Boulevard, Northridge, CA 91329 USA www.marklevinson.com

© 2021 HARMAN International Industries, Incorporated. All rights reserved. Mark Levinson is registered trademark of HARMAN International Industries, Incorporated. This document should not be construed as a commitment on the part of HARMAN International Industries, Incorporated. The information it contains, as well as the features, specifications and appearance of the product, is subject to change without notice. HARMAN International Industries, Incorporated, assumes no responsibility for errors that may appear within this document.

	Software Release Notes
Models Affected	No5101
Version	19

Version 19:

Change list:

#	Issue ID	Description
1	3128	Fix intermittent noise issue

Country Region: Europe, Korea

Filename: 20210819_NO5101_EUROPE_V19.fup

MCU Version: 2.6

File length: 73419935

MD5: c5d5945fe1df05fba221b3c9e12f7f00

Release Date: 2021-08-09

Country Region: United States

Filename: 20210819_NO5101_US_V19.fup

MCU Version: 2.6

File length: 73419967

MD5: c51105e89f22f374bd3a249157a2909c

Release Date: 2021-08-09

Country Region: Japan

Filename: 20210819_NO5101_JAPAN_V19.fup

MCU Version: 2.6


File length: 73419967

MD5: 5f2e593d9c05713671fbf2db0eecf3b6

Release Date: 2021-08-09

HARMAN International Industries, Incorporated, 8500 Balboa Boulevard, Northridge, CA 91329 USA www.marklevinson.com

© 2021 HARMAN International Industries, Incorporated. All rights reserved. Mark Levinson is registered trademark of HARMAN International Industries, Incorporated. This document should not be construed as a commitment on the part of HARMAN International Industries, Incorporated. The information it contains, as well as the features, specifications and appearance of the product, is subject to change without notice. HARMAN International Industries, Incorporated, assumes no responsibility for errors that may appear within this document.

	Software Release Notes
Models Affected	No5101
Version	19

Version 18:

Change list:

#	Issue ID	Description
1	3785	Sample rate is not displayed on Coax and Optical Inputs when the unit is taken out of standby and is on that input and that input is playing
2	3842	Disc Continues to spin indefinitely in standby

Country Region: Europe, Korea

Filename: 20201130_NO5101_EUROPE_V18.fup

MCU Version: 2.5

File length: 73419967

MD5: b912ac5f1cad6c40d9bee1f28edc12c2

Release Date: 2020-01-09

Country Region: United States

Filename: 20201130_NO5101_US_V18.fup

MCU Version: 2.5

File length: 73419951

MD5: 31177e0799dc9198d2d14ae0c6aca1d3

Release Date: 2020-01-09

Country Region: Japan

Filename: 20201130_NO5101_JAPAN_V18.fup

MCU Version: 2.5


File length: 73419887

MD5: 3716ff65843de0275011f367970d1634

Release Date: 2020-01-09

HARMAN International Industries, Incorporated, 8500 Balboa Boulevard, Northridge, CA 91329 USA www.marklevinson.com

© 2021 HARMAN International Industries, Incorporated. All rights reserved. Mark Levinson is registered trademark of HARMAN International Industries, Incorporated. This document should not be construed as a commitment on the part of HARMAN International Industries, Incorporated. The information it contains, as well as the features, specifications and appearance of the product, is subject to change without notice. HARMAN International Industries, Incorporated, assumes no responsibility for errors that may appear within this document.

	Software Release Notes
Models Affected	No5101
Version	19

Version 16

Change list:

#	Issue ID	Description
1	3716	Make default for Network Standby to be "Standby" (currently "Active")

Country Region: Europe, Korea

Filename: 20200915_NO5101_EUROPE_V16.fup

MCU Version: 2.4

File length: 73419878

MD5: 57ec6ff493f924808df55762fa00b2fe

Release Date: 2020-09-15

Country Region: United States

Filename: 20200915_NO5101_US_V16.fup

MCU Version: 2.4

File length: 73419878

MD5: 14c23a22716eba38563b9a2240c07ffb

Release Date: 2020-09-15

Country Region: Japan

Filename: 20200915_NO5101_JAPAN_V16.fup

MCU Version: 2.4


File length: 73419878

MD5: 924ac23caff7ea05147d781fa70afa86

Release Date: 2020-09-15

HARMAN International Industries, Incorporated, 8500 Balboa Boulevard, Northridge, CA 91329 USA www.marklevinson.com

© 2021 HARMAN International Industries, Incorporated. All rights reserved. Mark Levinson is registered trademark of HARMAN International Industries, Incorporated. This document should not be construed as a commitment on the part of HARMAN International Industries, Incorporated. The information it contains, as well as the features, specifications and appearance of the product, is subject to change without notice. HARMAN International Industries, Incorporated, assumes no responsibility for errors that may appear within this document.

	Software Release Notes
Models Affected	No5101
Version	19

Version 15

Change list:

#	Issue ID	Description
1		Japan added

Country Region: Europe, Korea

Filename: 20200915_NO5101_EUROPE_V16.fup

MCU Version: 2.4

File length: 73419878

MD5: 57ec6ff493f924808df55762fa00b2fe

Release Date: 2020-09-15

Country Region: United States

Filename: 20200915_NO5101_US_V16.fup

MCU Version: 2.4

File length: 73419878

MD5: 14c23a22716eba38563b9a2240c07ffb

Release Date: 2020-09-15

Country Region: Japan

Filename: 20200915_NO5101_JAPAN_V16.fup

MCU Version: 2.4

File length: 73419878

MD5: 924ac23caff7ea05147d781fa70afa86

Release Date: 2020-09-15

HARMAN International Industries, Incorporated, 8500 Balboa Boulevard, Northridge, CA 91329 USA www.marklevinson.com

© 2021 HARMAN International Industries, Incorporated. All rights reserved. Mark Levinson is registered trademark of HARMAN International Industries, Incorporated. This document should not be construed as a commitment on the part of HARMAN International Industries, Incorporated. The information it contains, as well as the features, specifications and appearance of the product, is subject to change without notice. HARMAN International Industries, Incorporated, assumes no responsibility for errors that may appear within this document.