

ARCAM

by



Arcam AVR11 Crestron Home Driver

Product Manual

<https://www.arcam.co.uk/range/hda.htm>

User Guide

Introduction

Package name (pkg) : AvReceiver_Arcam_AVR11_IP.pkg

Version : 1.5.3

Functionality Provided

The Crestron Home UI provides the following functionality:

- | |
|--|
| <ul style="list-style-type: none">- Volume Control- Local Input Switching- Bass and Trebel Control |
|--|

Installer Settings

The following User Attributes can be configured:

N/A

Support

This is for internal use to assist in supporting the driver.

Support

If you require support for this driver please fill in a support request at <https://janustechnology.co.uk/support/>

Please ensure you provide the following information.

- Driver version you are using.
- Platform you are using i.e. Crestron Home
- Firmware version of your Arcam Product.
- Firmware version of your Crestron system.
- A full description of the issue you are having and how to recreate the issue.

Change Log

Date 2022-06-15 - Version - 1.5.3

Version Tested

- AVR Firmware - 1.45/09
- Crestron Home Version - v3.013.0179

Enhancements

- N/A

Bug Fixes

- Fixed issue with drive filling CH Logs.

Exceptions

- N/A

Date 2021-07-07 - Version - 1.5.0

Version Tested

- AVR Firmware - 1.45/09
- Crestron Home Version - v3.008.0079
- Simpl Windows - 4.15
- Device Database: 200.90 (build: 200.9000.002.00)
- Crestron Database (cnctrldb22000.mdb) : 206.05 (build: 206.0500.004.00)
- Crestron Toolbox: 3.09p30 (build: 3.0930.0043.0)
- SIMPL+ Cross Compiler: 1.3
- Crestron SIMPL # Pro v2.000.0058
- SDK 8.0.0.2

Enhancements

- Debug using crestron home setup

Bug Fixes

- N/a

Exceptions

- N/a
-

Version Tested

- AVR Firmware - 1.45/09
- Crestron Home Version - v3.008.0079
- Simpl Windows - 4.15
- Device Database: 200.90 (build: 200.9000.002.00)
- Crestron Database (cnctrldb22000.mdb) : 206.05 (build: 206.0500.004.00)
- Crestron Toolbox: 3.09p30 (build: 3.0930.0043.0)
- SIMPL+ Cross Compiler: 1.3
- Crestron SIMPL # Pro v2.000.0058
- SDK 8.0.0.2

Enhancements

- Added Tone Ctls
- Added Audio Connections
- Separated Models in the PKG file

Bug Fixes

- N/a

Exceptions

- N/a

Date 2021-08-23 - Version - 1.4.4

Version Tested

- AVR Host 727
- Crestron Series 3 Processor Firmware - v1.502.3151.19579
- Crestron Series 4 Processor Firmware - v2.4617.00032
- Crestron Home Version - v3.007.0071
- Simpl Windows - 4.17
- Device Database - 200.9000.002.00
- Crestron Database - 206.0500.004.00
- Simpl+ - 4.06.00
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.17.00.05

Enhancements

- N/a

Bug Fixes

- Minor user guide changes

Exceptions

- N/a

Date 2021-08-19 - Version - 1.4.3

Version Tested

- AVR Host 727
- Crestron Series 3 Processor Firmware - v1.502.3151.19579
- Crestron Series 4 Processor Firmware - v2.4617.00032
- Crestron Home Version - v3.007.0071
- Simpl Windows - 4.17
- Device Database - 200.9000.002.00
- Crestron Database - 206.0500.004.00
- Simpl+ - 4.06.00
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.17.00.05

Enhancements

- Added new models

Bug Fixes

- N/a

Exceptions

- N/a

Date 2021-07-07 - Version - 1.4.2

Version Tested

- AVR Firmware - 1.45/09
- Crestron Series 3 Processor Firmware - v1.502.3151.19579
- Crestron Series 4 Processor Firmware - v2.4508.00035
- Crestron Home Version - v3.006.0132
- Simpl Windows - 4.15
- Device Database - 200.7000.003.00
- Crestron Database - 205.0000.004.00
- Simpl+ - 4.05.01
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2
- Smart Graphics Version - 2.15.04.00

Enhancements

- Manuals in the .pkg
- Change .pkg names

Bug Fixes

- N/a

Exceptions

- N/a

